Oklahoma Department of Mines

Safety-Gram

Title 45, Chapter 11

August 2012 Volume 13, Number 8

FIRE PREVENTION AND CONTROL

SECTION 910.B3 – Areas surrounding flammable liquid storage tanks and electric substations and transformers shall be kept free from dry grass, weeds, underbrush and other combustion materials for at least twenty-five (25) feet in all directions.