Awarded Vendor Information

				PAGE	O
Vendor Name: ⊢	Hall Manufacturing	Inc.	Vendor	I D# : 000007205	57
Vendor Address:	Address: P.O. E	Box 5638			
	City: North	Little Rock	State: AR	Zip Code: 72	119
Contact Person Name: R	Robert Hall		Phone #: 1- 501 - 945	5 - 7550	
Title: P	President		Fax #: 1- 501 - 945	5 - 0072	
Email: <u>r</u>	hall@bush-whacke	er.com			
Website: h	ttp://www.bush-wh	hacker.com			
Authorized Location:	Locations list at	ttached as One loc	ation, North Little rock, Arkansas	;	
	Address:				
City:			State:	Zip Code:	
Contract ID #:					
Delivery: F	OB Destination		Minimum Order: n/a		
P/Card Accepted:	☑ Yes	☐ No			
Other: S	Services the entire	State			
S	Services the followi	ing equipment: Bus	sh-Whacker mowers		
L	ead Time: 1 week				

CONTRACT



State of Oklahoma

Vendor ID 0000072057 HALL MANUFACTURING INC BUSH-WHACKER PO BOX 5638 NORTH LITTLE ROCK AR 72119-5638

Tax	Exempt? Y Tax Exempt	: ID:736017987					
١				Minimum Order		Maximum / Open	
Line	# Cat CD / Item ID / Item Des	ic		Qty	Amt	Qty	Amt
1	72151800 / 1000008833 SERVICE: Heavy Equip Me Repair Service Labor Rate per hour is \$90.0			1.00	0.00	0.00	0.00
	Contract Base Pricing	90.0000	A8 ·		0001		
2	72151800 / 1000008837 SERVICE: Heavy Equip Par Parts at list price less 20%.	ts Main. Repair		1.00	0.00	0.00	0.00
3	72151800 / 1000008835 SERVICE: Heavy Equip Ser Mile Service per mile if Supplier r location is \$2.50 per mile.	vice Rate Per epairs equipment at the Govel	rnment entity's	1.00	0.00	0.00	0,00
	Contract Base Pricing	2.50000	DH		0001		

COMMENTS:

SW-455-Non-Highway, Farm, Grounds and Heavy Construction Equipment Repair and Parts.

Hall Manufacturing, Inc. P O Box 5638 North Little Rock, AR 72119

Contact Person: Robert Hall Phone: 501-945-7550 Fax: 501-945-0077

Email: rhall@bush-whacker.com

Services all counties in Oklahoma.

Services the following equipment: Bushwhacker mowers.

Lead Time: 1 week.

Authorized Signature

Final = The price is final after adjustments

Hard = Apply adjustments regardless of other adjustments

Skip = Skip adjustments if any other adjustments have been applied