

Oklahoma Department of Mines – Coal Division

Enforcement Actions for 2011

5/20/2011

Farrell-Cooper 05/10-4274 – Kevin Woody

NOV 10-21-01 TV1 issued 02/24/10. **OSI: No off-site impact.**

1 of 1 – Failure to reclaim in a contemporaneous manner.

Abatement: 05/25/10.

Extended: 08/04/10. Operator submitted Recl. Schedule 05/26/10.

Extended: 10/15/10. Reclamation is on-going.

Extended: 12/15/10. As per reclamation agreement.

Extended: 02/28/11. As per reclamation agreement.

Extended: 06/15/11. As per reclamation agreement.

Farrell-Cooper 03/08-4263F – Kevin Woody

NOV 10-21-10 TV1 issued 11/16/10. **No off-site impact.**

1 of 1 – Failure to effectively secure surface facilities.

Abatement: 01/12/11.

Extended: 02/16/11.

Extended: 04/11/11.

Extended: 06/15/11. Over 90 days.

Phoenix Coal 08/13-4270 – Doug Cross

NOV 11-20-02 TV2 issued 04/25/11. **OSI: No off-site impact.**

1 of 2 – Failure to follow approved mine plan (unapproved culvert).

Abatement: 07/26/11.

2 of 2 – Failure to construct spillway on Pond #9 to the approved design.

Abatement: 07/26/11.

Farrell-Cooper 10/15-4280 - Kevin Woody

NOV 11-21-01 TV1 issued 04/29/2011. **OSI: Water-Hydro-Minor.**

1 of 1 – Construct/maintain diversion to apprvd design.

Abatement: 05/30/11.

Phoenix Coal 10/15-4283 – Doug Cross

NOV 11-20-03 TV1 issued 04/28/11. **OSI: No off-site impact.**

1 of 1 – Failure to certify Pond #55 built to design.

Abatement: 06/01/11.

Farrell-Cooper 06/11-4272 – Matt Moss

NOV 11-28-02 TV1 issued 05/02/11. **OSI: No off-site impact.**

1 of 1 – Failure to maintain sediment control structures.

Abatement: 05/27/11 to apply for revision.

Abatement: 07/01/11 for revision approval.

Farrell-Cooper 05/10-4274 – Kevin Woody

NOV 11-21-02 TV2 issued 05/17/11. **OSI: No off-site impact.**

1 of 2 – Failure to stabilize topsoil from wind/water erosion.

2 of 2 – Failure to construct/maintain inlet of final pit impoundment.

Abatement: 06/06/11.

Phoenix Coal 10/15-4283 – Doug Cross

NOV 11-20-04 TV1 issued 05/18/11. **OSI: No off-site impact.**

1 of 2 – Failure to follow approved mine plan Pond #53/Berm 53N.

Abatement: 08/17/11.